

Download Airbus Manual Release Tool

Nous développons présentement la version française de ce site. Cliquez ici info@airbus.com si vous désirez être avisé dès que celle-ci sera disponible. info@airbus.com si vous désirez être avisé dès que celle-ci sera disponible. ×SB 52-011 DOORS AND SERVICE COVERS – Pilot doors – Retrofitting of pilot-door locking devices on the pilot and co-pilot side. SB 31-043 Indicating and Recording Systems – Cockpit Voice and Flight Data Recorder (CVFDR). Safety First #26 / July 2018 - Look out for Ice Ridges on the Lower Nose Fuselage - High Load Event Reporting - Using Aircraft as a Sensor on Contaminated Runways - Thrust Reverser Deployment in Flight Download File 7.97 MB Customers require immediate access to operational and maintenance directives to keep their rotorcraft flying and to support flight safety. All the latest directives – such as alert service bulletins (ASBs), service bulletins (SBs) and safety information notices (SINs) – are published in real time on Airbus Helicopters' T.I.P.I. portal (Technical Information Publication on Internet).